


**Installation des Strahlungsschutz Shield Tamb-Si**  
(passend für Tamb-Si, Si-RS485TC-2T, Ta-ext-I(V)-4090 oder Ta-ext-RS485)

1. Entfernen des Kunststoffhalters am Tamb-Si,  
ACHTUNG: Den Kabelmantel nicht beschädigen!



2. Montieren der Kabelverschraubung (KVS) am unteren Halter.




3. Befestigung des Sensors Tamb-Si in der KVS. Die Sensorhülse sollte ca. 1 cm aus der KVS herausragen.



4. Installation der Halter am Strahlungsschutz.

5. Beachten Sie auch das "APRS6547 assembly sheet".




Alle Größen in mm

Gewicht: 270 g


## Installation of Radiation Shield Tamb-Si

(suitable for Tamb-Si, Si-RS485TC-2T, Ta-ext-I(V)-4090 or Ta-ext-RS485)

1. Remove the plastic holder of Tamb-Si, CAUTION: Do not damage the cable jacket!



2. Install the cable gland to the main bracket.




3. Install the Tamb-Si into the cable gland. The sensor tube should extend less than 1/2 inch out of the cable gland.

4. Install the main bracket and support bracket to the radiation shield.



5. Refer also to the APRS6547 assembly sheet.



All sizes in inch (mm)

Weight: 270 g